

CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM		Page <u>1</u> of <u>2</u>
Sewershed: Dundalk	Consultant: RJN Group, Inc.	Date: YYYYMMDD <u>2008 / 10 / 15</u>
Test to be performed: Smoke <u> </u> Dye <u>✓</u>	Ground Condition: Dry <u>✓</u> Damp <u> </u> Wet <u> </u>	Supervisor initials: <u>TS</u>
Manhole ID: <u>S69S-026MH</u>	Test ID: <u>D1047-019</u>	Notifications - made daily: <u>✓</u> (Residents, Fire, 311)

Field Sketch: Show all manholes with numbers, blower placement location, sandbag or isolation device location, street names, building addresses and locations, defect locations and photograph numbers.

Drainage Area
2054 Ft

(Pipe Broken at Surface)
Roof Drain/Downspouts
15 minute Test
30 gallon
DYE TEST positive

1717- Manor

Empty Lot
Demolished Buildings

DYE observed at MH # S69S-026

Eastbourne Ave

Manor Ave

S69S-026
Dye observed

S69S-012

Dye observed

rjngroup

CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM		Page <u>1</u> of <u>2</u>
Sewershed: Dundalk	Consultant: RJN Group, Inc.	Date: YYYYMMDD <u>2008 / 10 / 15</u>
Test to be performed: Smoke <u> </u> Dye <u>✓</u>	Ground Condition: Dry <u>✓</u> Damp <u> </u> Wet <u> </u>	Supervisor initials: <u>TS</u>
Manhole ID: <u>S69S-026MH</u>	Test ID: <u>D1047-019</u>	Notifications - made daily: <u>✓</u> (Residents, Fire, 311)
Field Sketch: Show all manholes with numbers, blower placement location, sandbag or isolation device location, street names, building addresses and locations, defect locations and photograph numbers.		



D1047-019-OB01-P01



D1047-019-OB01-P02